



TTI Performance Exhaust and Headers
Tube Technologies, Inc.
Corona, California 92880-1726
Phone (951) 371-4878
www.ttiexhaust.com

Sheet #C6573TSA

65-73 C-body, Column shift applications

TORQUE SHAFT ASSEMBLY

Part no: C6573TSA-7

Due to various manufacturing designs of the column shift linkage in some 65-73 C-body vehicles, a modified design Torque Shaft Assembly may be required.

A Torque Shaft Assembly is required if the drivers-side stock straight torque shaft rod is mounted below the torsion bar. The stock straight torque shaft rod passes directly through the space where the header tubes or exhaust pipe to manifolds, must go. The precision bent assembly with laser-cut ends allows you to maintain your column shift linkage, and is a direct bolt-on replacement of your stock straight torque shaft rod.



This side mounts to frame with factory bracket.

Bracket mounts to transmission, after removing factory bracket.

