



TTi Performance Exhaust and Headers
 Tube Technologies, Inc.
 Corona, California 92880-1726
 Phone (951) 371-4878
 www.ttiexhaust.com

71-74 B-body / 70-74 E-body
 Column shift applications

TORQUE SHAFT ASSEMBLY

Part no: B7174TSA-7 (727 Trans)
 Part no: B7174TSA-9 (904 Trans)

Due to various manufacturing designs of the column shift linkage in some 71-74 B-body and 70-74 E-body vehicles, a modified design Torque Shaft Assembly may be required.

A Torque Shaft Assembly is required if the drivers-side stock straight torque shaft rod is mounted below the torsion bar. The stock straight torque shaft rod passes directly through the space where the header tubes or exhaust pipe to manifolds, must go. This precision bent assembly with laser-cut ends allows you to maintain your column shift linkage, and is a direct bolt-on replacement of your stock straight torque shaft rod.

(!) The transmission rear rod to the modified design torque shaft assembly will require modification.

(!) This modified torque shaft assembly cannot be used with all headers. It will not clear the TTi big block 2.0" or 2-1/8" headers.



This side mounts to frame with factory bracket.

727 Bracket

904 Bracket

Bracket mounts to transmission, after removing factory bracket.



(!) The transmission rear rod to the modified design torque shaft assembly will require modification.

Modified rod - Top view looking down



Side view looking towards transmission



Torque shaft end

Transmission lever end